



#### Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations Revision date: 11/13/2015 Supersedes: not applicable Version: 1.0

## SECTION 1: Identification of the substance/mixture

#### **Product Identifier**

Product form: Plastic Abrasive Substance name: Magic® II Composite Blast Media (Type VIII) CAS No.: 9003-08-1 9011-05-6 9004-34-6 1318-93-0 Formula: H-[C10H8O4]-n=60–120 OH Synonyms: Material is a blend of thermoset plastics

Intended Use Of The Product

Use of the substance/mixture: Depainting

### Name, Address, And Telephone Of The Responsible Party

US Technology Media Inc. 509 Water ST., Bolivar OH. 44612 330-455-1181

#### **Emergency telephone number**

Emergency number : 330-874-3094 For Chemical Emergency, Spill, Leak, Fire, Exposure, or Accident, call US TECHNOLOGY – Day or Night

**SECTION 2: Hazards identification** 

#### Classification of the substance or mixture

**GHS-US classification** 

Eye Irrit. 2A H319

Label elements GHS-US labeling

Hazard statements (GHS-US)

: H319 - Abrasive Dust irritant: Causes serious eye irritation

Precautionary statements (GHS-US)

S) : P280 - Wear PPE - Dust mask and eye protection.

## SECTION 3: Composition/information on ingredients

Substances

Name	Product Identifier	%	GHS-US classification
w/Alpha Collulada Eillar and	(CAS No.)9003-08-1 9011-05-6 9004-34-6 <b>1318-93-0</b>	>1%	Amino Thermoset Molded Plastic
Acrylate Polymer – Polymerized and Cross-linked Alpha Cellulose Filler	25852-37-3	>1%	Amino Thermoset Molded Plastic
Anti-Static Agent – Cal Stat 600	2764-13-8	>1%	Amino Thermoset Molded Plastic
Pigments and Additives	5280-80-8 13463-67-7 12769-96-9	<2%	Amino Thermoset Molded Plastic

## SECTION 4: First aid measures

## Description of first aid measures

First-aid measures general: If material is airborne, remove person from exposure.

**First-aid measures after inhalation**: Go to well ventilated area, keep in a position for comfortable breathing, call Physician if symptoms persist.

First-aid measures after skin contact: Flush skin with water and soap.

**First-aid measures after eye contact**: Rinse cautiously for several minutes with water, remove contact lenses, if possible. **First-aid measures after ingestion**: Rinse mouth.

Most important symptoms and effects, both acute and delayed

Symptoms/injuries: Eye irritation.

Magic PowderBlast®

Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations

Symptoms/injuries after skin contact: Skin rash.

Symptoms/injuries after eye contact: Causes serious eye irritation.

#### Indication of any immediate medical attention and special treatment needed

If medical advice is needed, have product container or label at hand.

#### SECTION 5: Firefighting measures

#### Extinguishing media

Suitable extinguishing media: Alcohol foam, water, carbon dioxide, dry chemical. Unsuitable extinguishing media: None.

## Special hazards arising from the substance or mixture

Fire hazard: Highly flammable liquid and vapor.

Explosion hazard: Flame will form toxic vapors; avoid inhalation of smoke or vapors.

#### Advice for firefighters

Firefighting instructions: Exercise caution when fighting any chemical fire.

Protection during firefighting: Firefighters should wear full protective gear with independent breathing air.

## SECTION 6: Accidental release measures

#### Personal precautions, protective equipment and emergency procedures

**General measures**: Use special care to avoid static electric charges. Keep away from heat/sparks/open flames/hot surfaces. – No smoking. Avoid breathing. Use only in a well-ventilated area. Handle in accordance with good

industrial hygiene and safety practice.

#### For non-emergency personnel

Protective equipment: Use appropriate personal protection equipment (PPE).

Emergency procedures: Evacuate unnecessary personnel.

#### For emergency responders

**Protective equipment:** Equip cleanup crew with proper protection. Use appropriate personal protection equipment (PPE). **Emergency procedures:** Ventilate area.

#### **Environmental precautions**

Prevent entry to sewers and public waters.

#### Methods and material for containment and cleaning up

For containment: Contain spill, then place in suitable container. Sweep or vacuum.

Methods for cleaning up: Clear up spills immediately and dispose of waste safely.

#### **Reference to other sections**

See heading 8, Exposure Controls and Personal Protection.

### SECTION 7: Handling and storage

#### Precautions for safe handling

#### Additional hazards when processed: None.

**Precautions for safe handling:** Keep away from heat/sparks/open flames/hot surfaces. – No smoking. Avoid breathing. Use only in a well-ventilated area. Wear recommended personal protective equipment.

**Hygiene measures:** Handle in accordance with good industrial hygiene and safety procedures. Wash hands and other exposed areas with mild soap and water before eating, drinking, or smoking and again when leaving work.

#### Conditions for safe storage, including any incompatibilities

#### Technical measures: None.

Storage conditions: Store in a dry, cool and well-ventilated place. Keep container closed when not in use.

Incompatible products: Strong acids. Strong bases. Strong oxidizers.

Incompatible materials: Heat sources.

Storage area: Keep in dry place.

Special rules on packaging: None.

Specific end use(s): Filler.

#### Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations

JSA OSHA OSHA PEL (TV Exposure controls Appropriate engineering controls V Personal protective equipment	(ppm) (ppm) WA) (mg/m3)
JSA ACGIH       ACGIH TWA (         JSA ACGIH       ACGIH STEL (         JSA OSHA       OSHA PEL (TV)         JSA OSHA       OSHA PEL (TV)         Sxposure controls       State of the second se	(ppm) (ppm) WA) (mg/m3) WA) (ppm) : Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
JSA ACGIH       ACGIH TWA (         JSA ACGIH       ACGIH STEL (         JSA OSHA       OSHA PEL (TV)         JSA OSHA       OSHA PEL (TV)         Sxposure controls       State of the second se	(ppm) (ppm) WA) (mg/m3) WA) (ppm) : Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
JSA OSHA OSHA PEL (TV JSA OSHA OSHA PEL (TV JSA OSHA OSHA PEL (TV Exposure controls suppropriate engineering controls suppropriate engineering controls suppropriate engineering controls suppropriate engineering controls	WA) (mg/m3) WA) (ppm) : Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
JSA OSHA OSHA PEL (TV Exposure controls Appropriate engineering controls V ersonal protective equipment	WA) (ppm) : Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
JSA OSHA OSHA PEL (TV Exposure controls Appropriate engineering controls V ersonal protective equipment	WA) (ppm) : Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
ersonal protective equipment	: Ensure all national/local regulations are observed. Gas detectors should be used when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
ersonal protective equipment	when flammable gases/vapors may be released. Proper grounding procedures to avoid static electricity should be followed. Ensure adequate ventilation, especially in confined areas.
land protection	
ye protection	: Wear protective gloves. : Safety glasses. : Wear Long Sleeve Shirt.
	: If exposure limits are exceeded or irritation is experienced, NIOSH approved respiratory protection should be worn.
hermal hazard protection	: Wear suitable protective clothing.
-	: When using, do not eat, drink or smoke.
<b>SECTION 9: Physical and chemi</b>	
nformation on basic physical and chem	
Physical state	: Dry powder
Appearance	: Grey powder
Color	: Grey
)dor	: None
)dor threshold	: No data available
H	: No data available
Relative evaporation rate (butylacetate=1)	
Alting point	; 500 °F
	: No data available
reezing point	
Boiling point Tash Point	: Not applicable
	: Not applicable : No data available
Auto-ignition temperature Decomposition Temperature	: No data available
	: No data available
lammability (solid, gas)	
/apor pressure	: Not applicable. : No data available
Relative vapor density at 20 °C	
Relative density	: No data available
Density Aubility	: No data available
olubility	: Insolvable : No data available
og Pow	: No data available : No data available
og Kow Viscosity, kinomatic	: No data available : No data available
/iscosity, kinematic /iscosity, dynamic	: No data available : No data available
/iscosity, dynamic xplosive properties	: No data available : No data available
Dxidizing properties	: No data available
xplosive limits	
<b>Other information:</b> No additional information	: Not applicable

Other information: No additional information available

#### Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations

## SECTION 10: Stability and reactivity

Reactivity Non-reactive.

**<u>Chemical Stability</u>** Stable under recommended handling and storage conditions (see section 7).

Possibility Of Hazardous Reactions Non-reactive.

Conditions To Avoid Avoid ignition sources. Heat. Sparks. Open flame.

Extremely high or low temperatures. Incompatible Materials Strong acids. Strong bases. Strong oxidizers.

Hazardous Decomposition Products Carbon oxides (CO, CO2). May release flammable and toxic gases.

### **SECTION 11: Toxicological information**

#### Information on toxicological effects

Acute toxicity

: Not classified

Composite Blast media CAS No.: 9003-08-1 9011-05-6 9004-34-6 1318-93-0	
LD50 oral rat	No Data Available
LD50 dermal rabbit	No Data Available
LC50 inhalation rat (mg/l)	No Data Available

Skin corrosion/irritation: Not classified

Serious eye damage/irritation: Causes serious eye irritation.

Respiratory or skin sensitisation: Not classified

Germ cell mutagenicity: Not classified

Carcinogenicity: Not classified

Reproductive toxicity: Not classified

Specific target organ toxicity (single exposure): Not classified.

Specific target organ toxicity (repeated exposure): Not classified

Aspiration hazard: Not classified

Symptoms/injuries after inhalation: Causes coughing.

Symptoms/injuries after eye contact: Causes serious eye irritation.

Symptoms/injuries after ingestion: Ingestion may cause nausea, vomiting.

## **SECTION 12: Ecological information**

Toxicity

Composite Blast media CAS No.: 9003-08-1 9011-05-6 9004-34-6 1318-93-0	
LC50 fishes 1	No Data Available
EC50 Daphnia 1	No Data Available
LC50 fish 2	No Data Available
EC50 Daphnia 2	No Data Available

#### Persistence and degradability

Composite Blast media CAS No.: 9003-08-1 9011-05-6	9004-34-6 1318-93-0	
Persistence and degradability	Not	

#### **Bioaccumulative potential**

Composite Blast media CAS No.: 9003-08-1 9011-05-6 9004-34-6 1318-93-0	
BCF fish 1	No Data Available
Log Kow	No Data Available
Bioaccumulative potential	Not established
	· · · · · · · · · · · · · · · · · · ·

#### Mobility in soil

No additional information available

**Other adverse effects** 

Other information

: Avoid release to the environment.

## SECTION 13: Disposal considerations

#### Waste treatment methods

**Regional legislation (waste):** U.S. - RCRA (Resource Conservation & Recovery Act) - Basis for Listing – 40 CFR261.2 Characteristic solid hazardous waste for Cd if in excess of 1 ppm, Cr if in excess of 5 ppm, or Pb is in excess of 5 ppm.

Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations

SECTION 14: Transport inform	hation
In accordance with ICAO/IATA/DOT/TDG	
UN number	
UN-No.(DOT)	: Not applicable
DOT NA no.	Not applicable
UN proper shipping name	
Department of Transportation (DOT)	: 1 - Class 1 - Flammable and combustible liquid 49 CFR 173.120
Hazard Classes	PLASTIC POWDER
Hazardous labels (DOT)	: Irritant
Packing group (DOT)	: 1 - Low Danger
DOT Special Provisions (49 CFR 172.102) :	: IB2 - Authorized IBCs: Metal (31A, 31B and 31N); Rigid plastics (31H1 and 31H2); Composite (31HZ1). Additional Requirement:
	T4 - 2.65 178.274(d)(2) Normal 178.275(d)(3)
	TP1 - The maximum degree of filling must not exceed the degree of filling
	determined by the following: (image) Where: tr is the maximum mean bulk
	temperature during transport.
DOT Packaging Exceptions (49 CFR	: No Limitation
173.xxx)	
DOT Packaging Non Bulk (49 CFR	: No Limitation
173.xxx) DOT Packaging Bulk (49 CFR 173.xxx)	: No Limitation
Additional information	. NO LIMITATION
Emergency Response Guide (ERG)	: No Limitation
Number	
Other information	: No supplementary information available.
Transport by sea	
DOT Vessel Stowage Location	: Below deck
MFAG-No.	: Not applicable
Air transport	
DOT Quantity Limitations Passenger	: Not applicable
aircraft/rail (49 CFR 173.27)	
DOT Quantity Limitations Cargo aircraft only (49 CFR 175.75)	: Not applicable
SECTION 15: Regulatory infor	mation
US Federal regulations	
RCRA – Disposal per 40CFR 261.2	
Net Listed on the United States TSCA /T	avia Substances Control Act inventory

Not Listed on the United States TSCA (Toxic Substances Control Act) inventory

## US State regulations

ee etate regulations	
State or local regulations	U.S Massachusetts - Right To Know List
	U.S New Jersey - Right to Know Hazardous Substance
	List U.S Pennsylvania - RTK (Right to Know) List

## Safety Data Sheet

according to Federal Register / Vol. 77, No. 58 / Monday, March 26, 2012 / Rules and Regulations

Indication of changes	: 11/13/2015
Other information	: This document has been prepared in accordance with the SDS requirements of the OSH/ Hazard Communication Standard 29 CFR 1910.1200.
GHS Full Text Phrases	
Eye Irrit. 1	Mild eye damage/eye irritation Category 1
H319	Causes serious eye irritation
NFPA fire hazard	<ul> <li>Exposure could cause irritation but only minor residual injury even if no treatment is given.</li> <li>I jouids and solids that can be ignited under almost all ambient conditions.</li> </ul>
NFPA fire hazard NFPA reactivity	
	treatment is given. : 0 - Liquids and solids that can be ignited under almost all ambient conditions. : 0 - Normally stable, even under fire exposure conditions, and are not reactive
NFPA reactivity	treatment is given. : 0 - Liquids and solids that can be ignited under almost all ambient conditions. : 0 - Normally stable, even under fire exposure conditions, and are not reactive
NFPA reactivity HMIS III Rating	<ul> <li>treatment is given.</li> <li>: 0 - Liquids and solids that can be ignited under almost all ambient conditions.</li> <li>: 0 - Normally stable, even under fire exposure conditions, and are not reactive with water.</li> </ul>

environmental requirements only. It should not therefore be construed as guaranteeing any specific property of the product.

SDS US (GHS HazCom) - US Only